


Transducer Evaluation Report

Manufacturer: Aloka	Customer: Hadar Med	Contact:	
Probe Model: UST_9112-5	Address: Najara ST.		
Serial Number: M02467	City: 63824 TEL_AVIV	State: ISRAEL	Zip Code:
Test Date: 22.12.2009 13:14		Phone Number:	
Test ID: 4107	Operator: Renate Schweitzer	Fax Number:	
Purpose: Sonden Reparatur	DX/Comments: G17D20 > Leitungsbruch beim Knickschutz neben dem Sondengehäuse <		

Sensitivity



Mean: 0,267


Max: 0,828

Min: 0,020

Std Dev: 0,287

Gain: 17 dB

Capacitance



Mean: -413,202

Max: -387,000

Min: -430,000




Std Dev: 9,964

Test ID: 4107

Page 1 of 3


Operator: Renate Schweitzer

22.12.2009 13:14




First Element Number: 21

Pulse Waveform 1




Frequency Spectrum 1




Middle Element Number: 42

Pulse Waveform 2




Frequency Spectrum 2



Last Element Number: 63

Pulse Waveform 3



Frequency Spectrum 3

